PROJECT: SRHS ASS'Y NOMENCLATURE: DEC PANEL

ASS'Y P/H: 5114UE391

SHEET:

FMEA REF.	FHEA REV.	NAME OFY A DRAWING REF. DESIGNATION	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HDWR / FUNC. RATIONALE FOR ACCEPTANCE 2/1R CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS
170		SAFING SW. OTY-1 P/N CAE 87836 ED 92020 SHEET 2	MODE: PERMANENT SWITCH HARDWIRE: SAFING. CAUSE(S): (1) SWITCH FAILS TO SAFE. (2) 28V POLE FAIL TO SAFE. (3) 28V AUTO CONTACT O/C.	HARDWIRE SAFING INITIATED. ARM STOPS. COMPUTER SUPPORTED MODES LOST. LOSS OF LIMPING DURING END EFFECTOR CAPTURE. SAME AS ABOVE BUT MODE LIGHT REMAINS OM. SAME AS ABOVE. WORST CASE LOSS OF HISSION. LOSS OF COMPUTER SUPPORTED MODES. REDUMDANT PATHS REMAINING DIRECT AND BACKUP	DESIGN FEATURES TOGGLE SWITCHES USED ON THE DEC PANEL ARE HERMETICALLY SEALED, AND OF A MATURE AND PROVEN DESIGN. THESE SWITCHES ARE IN COMMON USE ON THE ORBITER VEHICLE. THE SWITCHES ARE CONTROLLED BY ROCKWELL INTERNATIONAL SPECIFICATION NG 452-0102 AND MAVE BEEN QUALIFIED TO THE REQUIREMENTS OF THIS SPECIFICATION. ELECTRICAL CONNECTIONS TO THE SWITCH ARE ACHIEVED BY MEANS OF SOLDERABLE TERMINALS. WIRING TO SWITCH TERMINALS UTILIZES NICKEL PLATED CONDUCTORS WITH A POLYAMID INSULATION. SOLDERING OF THE MICKEL PLATED WIRE TO THE SWITCH TERMINALS IS CONTROLLED BY CAP PROCESS SPECIFICATION PD 91059. THE WIRING HARNESS IS DESIGNED TO BE CAPABLE OF SEPARATE TESTING (FOR INSULATION RESISTANCE, DIELECTRIC STRENGTH, AND CONTINUITY). MOUNTING OF THE SWITCH TO THE DEC PANEL IS BY MEANS OF A 15/32 NOT WHICH ENGAGES A THREADED BUSHING ON THE SWITCH. A KEYED WASHER PROVIDES ROTATION RESISTANCE, DIELECTRIC STRENGTH, AND TOROUGHD, THE NUT IS STAKED TO THE PANEL BY A BLOG OF PROY ADMISTIVE. A STAINLESS STEEL GUARD PROTECTS THE SWITCH. LEVER AGAINST DAMAGE OR INADVERTENT OPERATION. ANALYSIS OF THE BASIC PANEL STRUCTURE HAS DEMONSTRATED THAT THERE ARE NO RESONANCES IN THE RELEVANT VIBRATION FREQUENCY SPECTRUM. THIS AMALYSIS HAS DEEN VERTITED BY VIBRATION TESTING OF THE DAC PANEL ASSEMBLY. APPLICATION ANALYSIS HAS CONFIRMED THAT ADEQUATE ELECTRICAL STRESS MARGINS ARE ACHIEVED. AT THE PART LEVEL, QUALIFICATION/CERTIFICATION HESISTANCE, DUTLEMENT INCLUDES: INSULATION RESISTANCE, DUTLEMENT INCLUDES: INSULATION RESISTANCE, MERCEN TO TABLE THE MICLUS STRENGTH, SUSTAINCH, AND SEAL THE STRENGTH, CONTACT RESISTANCE, CONTACT RESISTANCE, CONTACT RESISTANCE, CONTACT RESISTANCE, CONTACT PROSISTANCE, CONTACT RESISTANCE, CONTACT RESISTANCE, CONTACT PROSISTANCE, CONTA
PREPARED BI	Y: !	1FUG	SUPERCEDING DAT	E: 00 001 07	PATE - LA BOL 91

PROJECT: SRMS ASS'Y NOMENCLATURE: DEC PANEL

SYSTEM: D&C SUBSYSTEM ASS'Y P/N: 51140E391

FMEA REF.	FHEA REV.	NAME DIY & Drawing Réf. Designation	FAILURE MODE AND CAUSE	FAILURE EFFECT ON END 1TEM	HOUR / FUNC. RATIONALE FOR ACCEPTANCE 2/1R CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS
PREPARED B	Y: M	SAFING SW. DIY-1 P/N CAE 87838 ED 92020 SHEET 2	MODE: PERMANENT ASMITCH HAROWIRE SAFING. CAUSE(S): (1) SWITCH FAILS TO SAFE. (2) 28V POLE FAIL (4) SAFE. (3) 28V AUTO CONTACT O/C.	HARDWIRE SAFING INITIATED, A:M STOPS, COMPUTER SUPPORTED MODES LOST, LOSS OF LIMPING DURING END EFFECTOR CAPTURE. SAME AS ABOVE BUT MODE LIGHT REMAINS ON. SAHE AS ABOVE. WORST CASE LOSS OF MISSION, LOSS OF COMPUTER SUPPORTED MODES. REDUNDANT PATHS REMAINING DIRECT AND BACKUP	ACCEPTANCE TESTS THE HARDWARE ITEM IS SUBJECTED TO THE FOLLOWING ACCEPTANCE ENVIRONMENTAL TESTS AS PART OF THE DEC PANEL ASSEMBLY. "IBRATION: LEVEL AND DURATION - REFERENCE TABLE 1 O THERMAL: +110 DEGREES F TO PLUS 10 DEGREES F (2 CYCLES - 9.5 MRS/CYCLE.) THE DAC PANEL ASSEMBLY IS FURTHER TESTED AS PART OF THE RMS SYSTEM TESTS (TP518 RMS STRONGBACK TEST AND TP552 FLAT FLOOR TEST) WHICH VERTITES THE ASSENCE OF THE FAILURE MODE. OUALIFICATION TESTS THE SWITCH ITEM HAS BEEN QUALIFIED FOR ORBITER USE. THE DAC PANEL ASSEMBLY HAS BEEN SUBJECTED TO THE FOLLOWING OUALIFICATION TEST ENVIRONMENTS. O VIBRATION: LEVEL AND DURATION - REFERENCE TABLE 1 O SHOCK: 200/11 MS - 3 AXES (6 DIRECTIONS) O THERMAL: 130 DEGREES F TO -23 DEGREES F (12 HRS PER CYCLE) (6 CYCLES) O HUMIDITY: 95% (120 DEGREES F TO 32 DEGREES F CYCLE IN 16 HRS) 10 CYCLES TOTAL. O EMC: MIL-STO-461 AS MODIFIED BY SL-E-0002 (TEST CEOI, CEO2, CEO3, CS01 (DC/AC), CEO3, RS04) FLIGHT CHECKOUT PDRS OPS CHECKLIST (ALL VEHICLES) JSC 16987 DATE: 24 JUL 91 CIL REV: 3

PROJECT: SRMS ASS'Y NOMENCLATURE: DEC PANEL SYSTEM: D&C SUBSYSTEM ASS'Y P/N: 51140E391

SHEET: ___3 NAME, QTY, & DRAWING REF. **FMEA** FAILURE MODE FMEA **FAILURE EFFECT** HDWR / FUNC. RATIONALE FOR ACCEPTANCÉ REF. REV. AND 2/1R DESIGNATION CAUSE END ITEM CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS 170 1 SAFING SW. HODE: HARDWIRE SAFING **QA/INSPECTIONS** QTY-1 PERMANENT INITIATED. ARM P/H CAE STOPS. COMPUTER SWITCH 87838 HAROWIRE SUPPORTED MODES HERMETICALLY SEALED TOGGLE SWITCHES ARE PROCURED TO ROCKWELL SAFING. ED 92020 LOST. LOSS OF SPECIFICATION MC452-0102. AS REQUIRED BY CAE SPECIFICATION SHEET 2 LIMPING DURING PS87838. CAE PART NO. PS87838. QUALIFICATION AND ACCEPTANCE TESTING OF SWITCHES IS PERFORMED TO RI SPECIFICATION CAUSE(S): END EFFECTOR (1) SWITCH FAILS TO CAPTURE. MC452-0102. SAFE. SAME AS ABOVE RECEIVING INSPECTION VERIFIES THAT SWITCHES RECEIVED ARE AS IDENTIFIED IN THE PROCUREMENT DOCUMENTS, THAT NO PHYSICAL DAMAGE HAS OCCURRED TO SWITCHES DURING SHIPMENT, THAT THE RECEIVING DOCUMENTS PROVIDE ADEQUATE TRACEABILITY INFORMATION BUT MODE LIGHT (2) 28V POLE REMATHS ON. FAIL TO SAME AS ABOVE. SAFE. AND ACCEPTANCE TEST DATA IDENTIFIES ACCEPTABLE PARTS. (3) 28V AUTO WORST CASE PARTS ARE INSPECTED THROUGHOUT MANUFACTURE AND ASSEMBLY AS CONTACT O/C. APPROPRIATE TO THE MANUFACTURING STAGE COMPLETED, THESE LOSS OF INSPECTIONS INCLUDE. MISSION. LOSS COMPONENT MOUNTING TO FRONT PANEL INSPECTION, SOLDERING OF OF COMPUTER WIRES TO SWITCH CONTACTS, WIRE ROUTING, STRESS RELIEF OF WIRES ETC., OPERATORS AND INSPECTORS ARE TRAINED AND CERTIFIED TO SUPPORTED MODES. MASA NHB 5300.4(3A) STANDARD, AS MODIFIED BY JSCOBBOOA. REDUNDANT PATHS DHINIAMEN PRE-TEST INSPECTION OF DRC PANEL ASSY INCLUDES AN AUDIT OF LOWER TIER INSPECTION COMPLETION, AS BUILD CONFIGURATION VERIFICATION TO AS DESIGN ETC. (SPAR/GOVERNMENT REP. -DIRECT AND BACKUP MANDATORY INSPECTION POINT) A TEST READINESS REVIEW (TRR) WHICH INCLUDES VERIFICATION OF TEST PERSONNEL, TEST DOCUMENTS, TEST EQUIPMENT CALIBRATION/ VALIDATION STATUS AND HARDWARE CONFIGURATION IS CONVENED BY QUALITY ASSURANCE IN CONJUNCTION WITH ENGINEERING PRICABLE AND THE GOVERNENT REPRESENTATIVE PRIOR TO THE START OF ANY FORMAL TESTING (ACCEPTANCE OR QUALIFICATION). ACCEPTANCE TESTING (ATP) INCLUDES AMBIENT PERFORMANCE. THERMAL AND VIBRATION TESTING, (SPAR/GOVERNMENT REP. MANDATORY INSPECTION POINT). INTEGRATION OF ORC PANEL, RHC, THE AND HELD, INSPECTIONS ARE PERFORMED AT EACH STAGE OF INTEGRATION, WHICH INCLUDES GROUNDING CHECKS, INTER CONNECT CABLE VERIFICATION, CONNECTOR INSPECTION FOR BENT OR PUSHBACK CONTACTS ETC. SUB-SYSTEM PERFORMANCE TESTING (ATP), INCLUDES AN AMBIENT PERFORMANCE TEST. (MANDATORY ENSPECTION POINT). SRMS SYSTEMS INTEGRATION, THE INTEGRATION OF MECHANICAL ARM SUBASSEMBLIES AND THE FLIGHT CABIN EQUIPMENT TO FORM THE SRMS. INSPECTIONS ARE PERFORMED AT EACH PHASE OF INTEGRATION WHICH INCLUDES GROUNDING CHECKS, THRU WIRTING CHECKS, WIRING ROUTING, INTERFACE CONNECTORS FOR BENT OR PUSH BACK CONTACTS ETC. SRMS SYSTEMS TESTING - STRONGBACK AND FLAT FLOOR AMBIENT PERFORMANCE TEST. (SPAR/GOVERNMENT REP. - MANDATORY INSPECTION CINION

SUPERCEDING DATE: 06 OCT 87 PREPARED BY: MFWG

APPROVED BY: _

DATE: 24 JUL 91

CIL REV: _3

MEA IEF.	FMEA STOR	NAME OTY & DRAWING REF. DESIGNATION	FAILURE HODE ARD CAUSE	FAILURE EFFECT ON END ITEM	HDWR / FUNC. 2/1R CRITICALITY	RATIONALE FOR ACCEPTANCE SCREENS: A-PASS, B-PASS, C-PASS	
170		SAFING SW. OTY-1 P/N CAE 87838 ED 92020 SHEET 2	MODE: PERMANENT 'S SUITCH HAROWIRE SAFING. CAUSE(S): (1) SWITCH FAILS TO SAFE. (2) 28V POLE FAIL TO SAFE. (3) 28V AUTO CONTACT O/C.	HARDWIRE SAFING INITIATED. ARM STOPS. COMPUTER SUPPORTED MODES LOST. LOSS OF LIMPING DURING END EFFECTOR CAPTURE. SAME AS ABOVE BUT MODE LIGHT REMAINS ON. SAME AS ABOVE. WORST CASE LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES. REDUNDANT PATHS REMAINING DIRECT AND BACKUP	FAILURE HISTI	DRY	
PARED B		FMG	SUPERCEDING DAT	E. 06 OCT 87	APPROVED MY:	DATE: 24 JUL 91	CIL RE

KITIC	L ITE	M8 LIST	PI A:	ROJECT: <u>SRMS</u> SS'Y HOMENCLAYURE: <u>Di</u>	SYSTEM: D&C SUBSYSTEM ASS'Y P/H: 51140E391 SHEET:
I AŁI.	'MEA REV.	HAME GTY & DRAWING REF. DESIGNATION	FAILURE HODE AND CAUSE	FAILURE EFFECT ON END ETEM	HDWR / FUNC. RATIONALE FOR ACCEPTANCE 2/1R CRITICALITY SCREENS: A-PASS, B-PASS, C-PASS
170		SAFING SW. GIY-1 P/N CAE 87838 ED 92020 SHEET 2	MODE: PERMANENT SWITCH HARDWIRE SAFING. CAUSE(S): (1) SWITCH FAILS TO SAFE. (2) 28V POLE FAIL TO SAFE. (3) 28V AUTO CONTACT O/C.	HARDWIRE SAFING INITIATED. ARM STOPS. COMPUTER SUPPORTED MODES LOST. LOSS OF LIMPING DURING EMD EFFECTOR CAPTURE. SAME AS ABOVE BUT MODE LIGHT REMAINS ON. SAME AS ABOVE. WORST CASE LOSS OF MISSION. LOSS OF COMPUTER SUPPORTED MODES. REDUNDANT PATHS REMAINING DIRECT AND BACKUP	COMPUTER SUPPORTED MODES CANNOT BE USED TO COMPLETE THE MISSION. DIRECT DRIVE AND BACK-UP MODES REMAIN. IF PAYLOAD ATTACHED, THE ARM SHOULD BE MANEUVERED TO A SAFE POSITION FOR PAYLOAD RELEASE. LOSS OF MEKE REDUNDANT PATH RESULTS. IN BEING OWE FAILURE WAY FROM INABILITY TO CRADLE ARM. IF WITH SUBSEQUENT FAILURES ALL DRIVE MODES ARE LOST, THE ARM MAY BE JETTISONED. CREW ACTION USE DIRECT DRIVE. CREW TRAINING NONE MISSION CONSTRAINTS HOME EXERCISE DAC SAFING SWITCH. VERIFY HARDWIRE SAFING VOLTAGE AT DAC PANEL OUTPUT. CORRSD ONLINE INSTALLATION EXERCISE DAC SAFING SWITCH. VERIFY HARDWIRE SAFING VOLTAGE AT LONGERON INTERFACE. CHRSD ONLINE INSTALLATION OPERATE ONE JOINT IN SINGLE, WITH SAFING IN AUTO. VERIFY TACHOMETER SIGNATURE.